

Entergy Services, Inc.
Mail Unit L-ENT-24A
639 Loyola Avenue
New Orleans, LA 70113
Tel 504-576-4993
Fax 504-576-5123
e-Mail gpierc2@entergy.com

Gregory D. PierceDirector Transmission Compliance

July 23, 2009

VIA ELECTRONIC FILING

Kimberly D. Bose, Secretary Federal Energy Regulatory Commission 888 First Street, N.E. Washington, D.C. 20426

Re: Entergy Services, Inc.; Docket No. ER05-1065-000

Report of AFC-Related Errors

Dear Secretary Bose:

Pursuant to the Federal Energy Regulatory Commission's ("Commission") April 24, 2006 Order in *Entergy Services, Inc.*, 115 FERC ¶ 61,095 (2006) ("April 24 Order"), Entergy Services, Inc., acting as agent for the Entergy Operating Companies, hereby notifies the Commission it has recently become aware of the following AFC-related error.

In the April 24 Order, the Commission conditionally accepted Entergy's proposal to establish an Independent Coordinator of Transmission ("ICT") for the Entergy System. As the Commission is aware, the Southwest Power Pool, Inc. acts as Entergy's ICT. In the April 24 Order, the Commission imposed an obligation for Entergy to "notify the Commission, the ICT and the Users Group within 15 days if Entergy discovers that it has lost data, or reported inaccurate data, or otherwise believes that it has mismanaged data." See April 24 Order at P 110. Accordingly, Entergy submits the following explanation of recently discovered issue involving OASIS.

The Entergy Operating Companies include: Entergy Arkansas, Inc., Entergy Gulf States Louisiana, LLC, Entergy Louisiana, LLC, Entergy Mississippi, Inc., Entergy New Orleans, Inc., and Entergy Texas, Inc. The Entergy Operating Companies and Entergy Services, Inc. are referred to collectively herein as "Entergy."

Kimberly D. Bose, Secretary July 23, 2009 Page 2

OASIS Scenario Analyzer

On July 11, 2009, the Entergy System Operation Center (SOC) located in Pine Bluff, Arkansas performed its annual back up drill (Drill) for 2009 as required by Reliability Standard EOP-008. The Drill involved the deactivation of all systems and operations at the SOC while simultaneously activating all systems and operations at Entergy's Back up Center located in West Monroe, Louisiana (:the Back up Center). From approximately 1:46 AM until 8:22 AM on July 11, all system operations for Entergy normally performed at its SOC were being performed at the Back up Center. During this time period, Entergy determined that its OASIS Scenario Analyzer was not functioning properly. Upon returning operations to the SOC from the Back up Center, Entergy determined that its OASIS Scenario Analyzer functionality was fully restored.

In the event that further information is needed, please do not hesitate to contact the undersigned.

Respectfully submitted, /s/Gregory D. Pierce Gregory D. Pierce Director, Transmission Compliance

cc: Southwest Power Pool, Inc.
ICT Users Group
Service List; Docket No. ER05-1065-000

CERTIFICATE OF SERVICE

I hereby certify that I have this 23rd day of July, 2009, served the foregoing document upon the Southwest Power Pool, Inc., the ICT Users Group, and each person designated on the official service list compiled by the Secretary in this proceeding.

/s/ Nicole A. Livaccari

Nicole A. Livaccari Mail Unit L-ENT-24A New Orleans, LA 70113

Tel: (504) 576-4296