



Entergy Services, Inc.
Mail Unit L-ENT-24A
639 Loyola Avenue
New Orleans, LA 70113
Tel 504-576-4993
Fax 504-576-5123
e-Mail gpierc2@entergy.com

Gregory D. Pierce
Director Transmission Compliance

March 16, 2010

VIA ELECTRONIC FILING

Kimberly D. Bose, Secretary
Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, D.C. 20426

Re: Entergy Services, Inc.; Docket No. ER05-1065-000
Report of AFC-Related Errors

Dear Secretary Bose:

Pursuant to the Federal Energy Regulatory Commission's ("Commission") April 24, 2006 Order in *Entergy Services, Inc.*, 115 FERC ¶ 61,095 (2006) ("April 24 Order"), Entergy Services, Inc., acting as agent for the Entergy Operating Companies,¹ hereby notifies the Commission it has recently become aware of the following AFC-related error.

In the April 24 Order, the Commission conditionally accepted Entergy's proposal to establish an Independent Coordinator of Transmission ("ICT") for the Entergy System. As the Commission is aware, the Southwest Power Pool, Inc. acts as Entergy's ICT. In the April 24 Order, the Commission imposed an obligation for Entergy to "notify the Commission, the ICT and the Users Group within 15 days if Entergy discovers that it has lost data, or reported inaccurate data, or otherwise believes that it has mismanaged data." See April 24 Order at P 110. Accordingly, Entergy submits the following explanation of inaccurate posting of data.

¹ The Entergy Operating Companies include: Entergy Arkansas, Inc., Entergy Gulf States Louisiana, LLC, Entergy Louisiana, LLC, Entergy Mississippi, Inc., Entergy New Orleans, Inc., and Entergy Texas, Inc. The Entergy Operating Companies and Entergy Services, Inc. are referred to collectively herein as "Entergy."

Kimberly D. Bose, Secretary
March 16, 2010
Page 2

Displaced Redirects in WebTrans

On March 2, 2010, during the testing of a new release of webOASIS and subsequent discussions with OATi, it was determined that webOASIS was configured, prior to March 3, 2010, to return capacity that is “DISPLACED” from a reservation redirected on a firm basis to the parent reservation from which the redirected reservation originated. Accordingly, the capacity available profile on the parent reservation that had been decremented to support the redirected reservation was incremented when the redirect reservation was “DISPLACED”. This change in available profile value was not reflected in the capacity available value posted on Entergy’s webOASIS.

The new release of webOASIS Version 3.4.12 that corrected the issue was placed into production on March 3, 2010. Three redirected reservations were identified that are active. These reservations are being reviewed by Entergy to identify compensatory measures.

Respectfully submitted,
/s/Gregory D. Pierce
Gregory D. Pierce
Director, Transmission Compliance

cc: Southwest Power Pool, Inc.
ICT Users Group
Service List; Docket No. ER05-1065-000

CERTIFICATE OF SERVICE

I hereby certify that I have this 16th day of March, 2010, served the foregoing document upon the Southwest Power Pool, Inc., the ICT Users Group, and each person designated on the official service list compiled by the Secretary in this proceeding.

/s/ Nicole A. Livaccari

Nicole A. Livaccari
Mail Unit L-ENT-24A
New Orleans, LA 70113
Tel: (504) 576-4296