



Entergy Services, Inc.
Mail Unit L-ENT-24A
639 Loyola Avenue
New Orleans, LA 70113
Tel 504-576-4993
Fax 504-576-5123
e-Mail gpierc2@entergy.com

Gregory D. Pierce
Director Transmission Compliance

June 25, 2012

VIA ELECTRONIC FILING

Kimberly D. Bose, Secretary
Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, D.C. 20426

Re: Entergy Services, Inc.; Docket No. ER05-1065-000
Report of AFC-Related Errors

Dear Secretary Bose:

Pursuant to the Federal Energy Regulatory Commission's ("Commission") April 24, 2006 Order in *Entergy Services, Inc.*, 115 FERC ¶ 61,095 (2006) ("April 24 Order"), Entergy Services, Inc., acting as agent for the Entergy Operating Companies,¹ hereby notifies the Commission it has recently become aware of the following AFC-related error.

In the April 24 Order, the Commission conditionally accepted Entergy's proposal to establish an Independent Coordinator of Transmission ("ICT") for the Entergy System. As the Commission is aware, the Southwest Power Pool, Inc. acts as Entergy's ICT. In the April 24 Order, the Commission imposed an obligation for Entergy to "notify the Commission, the ICT and the Users Group within 15 days if Entergy discovers that it has lost data, or reported inaccurate data, or otherwise believes that it has mismanaged data." See April 24 Order at P 110. Accordingly, Entergy submits the following summary of inaccurate data.

¹ The Entergy Operating Companies include: Entergy Arkansas, Inc., Entergy Gulf States Louisiana, LLC, Entergy Louisiana, LLC, Entergy Mississippi, Inc., Entergy New Orleans, Inc., and Entergy Texas, Inc. The Entergy Operating Companies and Entergy Services, Inc. are referred to collectively herein as "Entergy."

Kimberly D. Bose, Secretary
June 25, 2012
Page 2

Flowgate Rating

On June 11, 2012, Entergy identified that the NBHOL_HARCYP flowgate rating was incorrect. A notice was received to change the rating from 275MVA to 273MVA. The models for the Operating, Planning and Study Horizons were not updated to reflect the change. The error existed from May 24, 2012 until corrected on June 11, 2012 for the Operating, Planning and Study Horizons.

This error may have resulted in incorrect AFC values for this flowgate anytime a customer requested service that impacted this flowgate. The error may have potentially resulted in more AFCs available since the incorrect rating was 2MVA higher on the flowgate than the actual value. It is not technically feasible to determine the exact impact.

In the event that further information is needed, please do not hesitate to contact the undersigned.

Respectfully submitted,
/s/Gregory D. Pierce
Gregory D. Pierce
Director, Transmission Compliance

cc: Southwest Power Pool, Inc.
ICT Users Group
Service List; Docket No. ER05-1065-000

CERTIFICATE OF SERVICE

I hereby certify that I have this 25th day of June, 2012, served the foregoing document upon the Southwest Power Pool, Inc., the ICT Users Group, and each person designated on the official service list compiled by the Secretary in this proceeding.

/s/ Nicole A. Livaccari

Nicole A. Livaccari
Mail Unit L-ENT-24A
New Orleans, LA 70113
Tel: (504) 576-4296