

**MIDWEST ISO Flowgate Changes**

There is an increase in capability of the following flowgates due to recent transmission upgrade projects.

NERCID	FGNAME	TYPE	OWNER	RCF
3802	NAppleton_Fox345 flo_NAppleton_Kewaunee345	OTDF	MISO	MISO,MAPP
3518	BUTLER GRANVILE ARCADIAN GRANVILE	OTDF	MISO	MISO,MAPP
3113	NEWTON-CASEY 345 KV	PTDF	MISO	MISO,PJM,TVA

The reason for the change in ratings includes change in terminal equipments or an upgrade conducted on the lines by the Transmission owner.

These changes will be effective from Oct 1<sup>st</sup> 2008.

**Reflecting the new facility ratings in the MISO ASTFC process:**

The MAPP-MISO Seams Agreement provides a mechanism whereby parties that pay to increase the capability of a flowgate would undergo an allocation adjustment as put forth by the CMPWG members. The Reciprocal entities will then receive an increase/decrease in allocation as per the rules laid out in the white paper titled “Allocation Adjustments for New Transmission Facilities”. Since the allocation adjustments for new transmission facilities issue is still under discussion, the increase in rating i.e., the additional STFC will be assigned to Midwest ISO until the process is finalized. Midwest ISO staff will maintain the information showing the additional STFC values allocated to Midwest ISO on the above Flowgates. Change in ASTFC values that result from the increase in MISO STFC is available for sharing or transfer to other reciprocal entities as per the Seams Operating Agreements to accommodate requests for new transmission service.