

Morgan, Lewis & Bockius LLP
1111 Pennsylvania Avenue, NW
Washington, DC 20004
Tel. 202.739.3000
Fax: 202.739.3001
www.morganlewis.com

Morgan Lewis
C O U N S E L O R S A T L A W

Floyd L. Norton, IV
Partner
202.739.5620
fnorton@morganlewis.com

July 25, 2008

VIA ELECTRONIC FILING

Kimberly D. Bose, Secretary
Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, D.C. 20426

Re: Entergy Services, Inc.; Docket No. ER05-1065-000
 Report of AFC-Related Error

Dear Secretary Bose:

Pursuant to the Federal Energy Regulatory Commission's ("Commission") April 24, 2006 Order in *Entergy Services, Inc.*, 115 FERC ¶ 61,095 (2006) ("April 24 Order"), Entergy Services, Inc., acting as agent for the Entergy Operating Companies,¹ hereby notifies the Commission it has recently become aware of an error in the AFC process involving the participation factor data file.

In the April 24 Order, the Commission conditionally accepted Entergy's proposal to establish an Independent Coordinator of Transmission ("ICT") for the Entergy System. As the Commission is aware, the Southwest Power Pool, Inc. acts as Entergy's ICT. In the April 24 Order, the Commission imposed an obligation for Entergy to "notify the Commission, the ICT and the Users Group within 15 days if Entergy discovers that it has lost data, or reported inaccurate data, or otherwise believes that it has mismanaged data." *See* April 24 Order at P 110. Accordingly, Entergy submits the following explanation of a data error involving the participation factor file.

¹ The Entergy Operating Companies include: Entergy Arkansas, Inc., Entergy Gulf States Louisiana, LLC, Entergy Louisiana, LLC, Entergy Mississippi, Inc., Entergy New Orleans, Inc., and Entergy Texas, Inc. The Entergy Operating Companies and Entergy Services, Inc. are referred to collectively herein as "Entergy."

Kimberly D. Bose, Secretary
July 25, 2008
Page 2

Morgan Lewis
C O U N S E L O R S A T L A W

Participation Factor File Data Error

On January 22, 2008, the name of the NELSON plant in the EMS model was changed from NEL to NELSON. However, the offline process that creates the participation factor file for use in RFLOADER was not updated to reflect this new plant name. Thus, due to the name change, when RFLOADER processed data, a match for plant name NEL in the EMS models was not found. Accordingly, the participation factor data for the NELSON plant's two units was not appended to the unit commitment file used by RFCALC. On July 10, 2008, Entergy became aware of this situation through the ICT's research and analysis of a customer-identified issue pertaining to the publicly available participation factor file posted on OASIS. This participation factor file data error impacted response factor values calculated by RFCALC. At this time, which response factors were impacted and the effect this error had on these response factors is unknown. It is also unknown at this time what effect, if any, the impacted response factors may have had on any transmission service requests.

In the event that further information is needed, please do not hesitate to contact the undersigned.

Respectfully submitted,
/s/ Floyd L. Norton, IV
Floyd L. Norton
Attorney for
Entergy Services, Inc.

cc: Southwest Power Pool, Inc.
ICT Users Group
Service List; Docket No. ER05-1065-000

CERTIFICATE OF SERVICE

I hereby certify that I have this 25th day of July, 2008, served the foregoing document upon the Southwest Power Pool, Inc., the ICT Users Group, and each person designated on the official service list compiled by the Secretary in this proceeding.

/s/ Kevin C. Frank
Kevin C. Frank
Morgan, Lewis & Bockius LLP
1111 Pennsylvania Ave., N.W.
Washington, D.C. 20004
Tel: (202) 739-5709