

Notice of Disclosure

Due to a computer networking problem on July 25 and 26, 2005, PSE's merchant function was unable to obtain a print-out of their next-day schedules. PSE's transmission function was able to print-out schedules and faxed a copy to the PSE merchant on these two days. Subsequently, it was noticed by PSE management that these next-day control area schedule printouts contained not only PSE's merchant function's schedules, but all schedules into, out of, and through PSE's control area – including schedules of OATT customers and net interchange values with adjacent control areas. The information that was inadvertently sent to the merchant function is posted in the PSEI's Standards of Conduct folder, Deviations subfolder, at <http://www.oatioasis.com/psei/index.html>.