## Suspension of Code of Conduct for AMRN (09/08/07)

Due to the outage of a 345kv facility at a generating station MISO is suspending the Code of Conduct at AMRNIL temporarily.

As of 0444 on 09/09/2007, the Code of Conduct has been reinstated for AMRNIL.